




Re: FW: 902206 Pine View.pdf 

Aaron Setran to: Brenda Stein

Cc: David Albright, Rich Campbell

03/05/2009 02:52 PM

 Aaron Setran *Brenda: Based on the attached sampling results, and those related to L*

1 attachment



902206 Pine View.pdf

Brenda:

Based on the attached sampling results, and those related to December '08 and January '09, I think there is either something wrong with the main treatment unit or the way in which the effluent samples are being obtained. This needs to be explored immediately. It's mind-boggling that effluent samples can consistently yield higher values than influent samples for BOD and TSS. The monitoring well results for bact. and nitrogen all look good, that is, they are within acceptable levels. However, it's quite possible that the treatment unit for Field B is not functioning properly and that requires significant attention/action on PTP's part. Please provide me with an up-date as soon as possible. Thanks, Aaron

Aaron Carr Setran
U.S. EPA, Water Division
75 Hawthorne St.
San Francisco, CA 94105
(415) 972-3457

"Brenda Stein" <brenda@exdengineering.com>

"Brenda Stein" <brenda@exdengineering.com>

03/05/2009 11:18 AM

To Aaron Setran/R9/USEPA/US@EPA

cc

Subject FW: 902206 Pine View.pdf

Here is the partial report. It includes everything but the Coliphage. There still seems to be an issue. I hope to talk with you soon.

Brenda Stein P.E., M.B.A.
Principal Engineer
brenda@exdengineering.com



EXD Engineering & Land Surveying, Inc.

1641 Mono Avenue Minden, Nevada 89423
Ph: (775) 783-4772 Fx: (775) 783-4773

From: Cassie Cummings [<mailto:cassiec@wetlaboratory.com>]

Sent: Thursday, March 05, 2009 10:45 AM

To: Brenda Stein

Subject: 902206 Pine View.pdf

Hi Brenda,

Here is a preliminary report (partial).

Thanks,

Cassie Cummings

Western Environmental Testing Laboratory

775-355-0202 (phone)

775-355-0817 (fax)

cassiec@wetlaboratory.com (See attached file: 902206 Pine View.pdf)

